







# Crimp Instructions

1	<p>Begin with crimp sitting flat and the barrel at the top.</p>	
2	<p>Insert wire through the barrel. The wire can go through to the opposite end of the barrel <b>OR</b> through the hole at the top of the barrel.</p>	
3	<p>Loop the wire back through the barrel.</p>	
4	<p>Pull the wire through so only a small part of the loop can be seen.</p>	
5	<p>Crimp by coming down from the top and crushing the barrel using pliers.</p>	
	<p>The 3 legs allow for soldering lead wires or common header pin connectors.</p>	 <p><b>Ok to solder only at legs.</b></p>